



N64W23760 Main Street
Sussex, Wisconsin 53089
Phone (262) 246-5200
FAX (262) 246-5222
Email: info@villagesussex.org
Website: www.villagesussex.org

Public Service Commission of Wisconsin
RECEIVED: 11/17/16, 3:57:49 PM

Good Hope Road Crossing of Wisconsin Central Ltd. Tracks
Photographs taken November 15, 2016
Photo Record 1



1 - Good Hope Road Looking West



2 - Good Hope Road Looking East



3 - Wisconsin Central Ltd. Tracks Looking North



4 - Wisconsin Central Ltd. Tracks Looking South

Good Hope Road Crossing of Wisconsin Central Ltd. Tracks
Photographs taken November 15, 2016
Photo Record 2



1 - Looking South Showing 4 feet from outside rail



2 - Looking North Showing 4 feet from outside rail



N64W23760 Main Street
Sussex, Wisconsin 53089
Phone (262) 246-5200
FAX (262) 246-5222
Email: info@villagesussex.org
Website: www.villagesussex.org

Good Hope Road Crossing of Wisconsin Central Ltd. Tracks
Photographs taken November 15, 2016
Photo Record 3



1 - Looking South - Note Crossing Material Broken and Offset




2 - Note Offset Depth of 3 inches

Good Hope Road Crossing of Wisconsin Central Ltd. Tracks
Photographs taken November 15, 2016
Photo Record 4



1 - Crossing material not stable - not missing bolts



2 - Crossing Material not stable - note offset in crossing material and missing bolts



3 - Asphalt Edges broken - Note 10 inch depth of hole



4 - Asphalt Edges broken - Note 6 inch hole (typical)

Good Hope Road Crossing of Wisconsin Central Ltd. Tracks
Photographs taken November 15, 2016
Photo Record 5



1 - South Side Good Hope - Note gravel shoulders not level with roadway pavement



2 - South Side Good Hope - Note gravel shoulder not level with roadway pavement



3 - North Side Good Hope - Note gravel shoulders not level with roadway pavement



4 - North Side Godd Hope - Note gravel shoulders not level with roadway pavement



N64W23760 Main Street
Sussex, Wisconsin 53089
Phone (262) 246-5200
FAX (262) 246-5222
Email: info@villagesussex.org
Website: www.villagesussex.org

Good Hope Road Crossing of Wisconsin Central Ltd. Tracks
Photographs taken November 15, 2016
Photo Record 6



1 - Pedestrian Crossing Looking South - Note rubber gaskets have shifted and asphalt path is settled and broken at crossing



2 - Pedestrian Crossing Looking East - Note crossing material not consistent width and contain no shouldering material



3 - Pedestrian Crossing - Note 6 inch depth of gap between rail and crossing material and gap between rail and crossing material



4 - Pedestrian Crossing - Note broken crossing material and lack of shouldering material